Thursday, 31/07/2008 1:38:34 PM

Julie Lecoco

Process Sheet



: CU-DAR001, Dart Helicopters Services

S.O. No. :

Type

Job Number

: 40861 ~ 🚜

Estimate Number

: 10429

P.O. Number This Issue

Previous Run

: 31/07/2008 : NC

Prsht Rev. First Issue

: 31/07/2008

: 40520

Written By Checked & Approved By

Comment

: Est: D 04.11.26

Revised Step 7

· MACHINED PARTS

KJ/JLM

Drawing Name

: TUBE ASSEMBLY

Part Number

: D3304043

Drawing Number

: D3304 REV. B : N/A

Project Number **Drawing Revision**

: B Material

: 08/08/2008 **Due Date**

Additional Product

Job Number:



Seq. #:

1-30

1.0

Machine Or Operation:

Description:

M304TR0875W065

304 round tune .875 x .065w

Comment: Qty.:

1.9469 f(s)/Unit Total: 17.5222 f(s)

Material: AISI 304/316 SS tubing 0.875" x 0.065" wall

(M304TR0.875W.065)

Batch: 1109007

2.0

BAND SAW

BAND SAW



Comment: BAND SAW

1- Cut blank: 22.00" as per Dwg D3304



3.0

LATHE CONV.

CONVENTIONAL LATHE



Comment: CONVENTIONAL LATHE

1- Cut blank: 22.00" as per Dwg D3304

2- Turn as per Dwg D3304

3- Deburr



QC2

Comment: INSPECT PARTS AS THEY COME OFF MACHINE



5.0

4.0

SECOND CHECK



Comment: SECOND CHECK



Thursday, 31/07/2008 1:38:34 PM Julie Lecocq

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services Drawing Name: TUBE ASSEMBLY Job Number: 40861 Part Number: D3304043 Job Number: Seq. #: Machine Or Operation: Description: SMALL FAB 1 6.0 SMALL & MEDIUM FAB RESOURCE 1 Comment: SMALL & MEDIUM FAB RESOURCE 1 1- Form as per Dwg D3304 08/08/25 08/08/25 Ensure that bend radius does not fall into straight section using DT8756. 2- Drill as per Dwg D3304 using drill Jig D3304-T1 3- Cut tube to length as per Dwg D3304 4- Deburr 7.0 QC5 INSPECT WORK TO CURRENT STEP Comment: INSPECT WORK TO CURRENT STEP 8.0 D33047 Bracket Comment: Qty.: 1.0000 Each(s)/Unit Total: 9.0000 Each(s) Bracket Pick: Qty Part Number Description Batch D3304-7 Bracket LARGE FAB 1 9.0 LARGE FABRICATION RESOURCE 1 Comment: LARGE FABRICATION RESOURCE 1 Weld bracket as per Dwg D3304 and QSI 004 using DT8775 10.0 QC9 VISUAL WELDING INSPECTION Comment: VISUAL WELDING INSPECTION 05-05-250 11.0 POWDER COATING POWDER COATING Comment: POWDER COATING Powder Coat Grey Sandtex (Ref: 4.3.5.6) as per QSI 005 4.3 START TIME:

OVEN TEMPERATURE:

FINISH TIME:

m. 1 08/08/28

Process Sheet

Drawing Name: TUBE ASSEMBLY Customer: CU-DAR001 Dart Helicopters Services Job Number: 40861 Part Number: D3304043 Job Number: Description: Seq. #: Machine Or Operation: INSPECT POWDER COAT/CHEMICAL CONVERSION 12.0 QC3 Comment: INSPEC BLBS0016 PIP PIN 13.0 Comment: Qty.: 1.0000 Each(s)/Unit Total: 9.0000 Each(s) PIP PIN Pick: Description Batch Qty Part Number m103178 1 BLBS-0016 Pip Pin 14.0 CBL460 Loop Sleeve Comment: Qty.: 2.0000 Each(s)/Unit Total: 18.0000 Each(s) Loop Sleeve Pick: Description Batch Qty Part Number SAD CBL-460 Loop Sleeve 2 n 107 CBL1240 Cable 15.0 Comment: Qty.: Total: 9.3744 f(s) 1.0416 f(s)/Unit Cable Pick: Batch Qty Part Number Description 1103927 12.5" CBL-1240 Cable SMALL & MEDIUM FAB RESOURCE 1 16.0 SMALL FAB 1 Comment: SMALL & MEDIUM FAB RESOURCE 1 Assemble lanyard and pip pin as per Dwg D3304 Identify as D3304-043 INSPECT WORK TO CURRENT STEP 17.0 QC5 Comment: INSPECT WORK TO CURRENT STEP

Thursday, 31/07/2008 1:38:34 PM Julie Lecocq

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: TUBE ASSEMBLY

Job Number: 40861

Part Number: D3304043

Job Number:



Seq. #:

Machine Or Operation:

Description:

18.0

PACKAGING 1

PACKAGING RESOURCE #1

Comment: PACKAGING RESOURCE #1

Identify with P/N and B/N as per Dwg using a permanent fine point marker, then Stock

Location:

85/80/80

QC21 19.0





Comment: FINAL INSPECTION/W/O RELEASE



30180


Job Completion



W 68, 04.29


DART AEROSPACE LTD	Work Order:	HENDERI
Description: Tube Assembly		Thomas
	Part Number:	D3304-3
Inspection Dwg: D3304 Rev: B	the second second	
1411,401		Page 1 of


	FIRST ARTICLE INSPECTION O				Prototype		
Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments	
9.25	+/-0.030	325	/		mapection		
Ø0.840	+/-0.010	9.841	/				
Ø0.875	+/-0.010	878	//				
0.065	+/-0.010	-065	/				
						- M	
			7				
ured by:		Audited by:	38,	Pro	totype Approval:	N/A	
Date Cha	38/24	Date: 08	104/20		Date:	N/A N/A	
	A CONTRACTOR OF THE PARTY OF TH	P/O D3304-043/	1011		Revised b	y Approve	






DESIGN RF	DRAWN BY		SPACE LTD DITARIO, CANADA
CHECKED	APPROVED IN	DRAWING NO. D3304	REV. B SHEET 3 OF 4
DATE 05.07.15		TUBE ASSEMBLY	SCALE 1:4







D3304-3 TUBE

SHOP COPY RETURN TO ENGINEERING UNCONTROLLED COPY SUBJECT TO AMENDMENT WITHOUT NOTICE WORK ORDER

D3304-3 NOTES:

- 1) MATERIAL: AISI 304/316 STAINLESS STEEL TUBE \$0.875 x 0.065 WALL (REF. DART SPEC M304TRO.875W.065) ENSURE SEAMLESS TUBE IS USED
- 2) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 3) ALL DIMENSIONS ARE IN INCHES
- 4) BREAK ALL SHARP EDGES 0.005 TO 0.015
- 5) BEND LINES 9.625, 13.375 DIMENSIONS

Copyright © 2004 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.